

SECRET 012207Z CITE [REDACTED] 8334

1966 SEP 1 22 27Z

OUT59671

1
25X1
25X1

1. CAMERA B-23 WAS USED IN MISSION GL 8117 FLOWN ON 30 AUGUST 1966. PROCESSING WAS ACCOMPLISHED BY BARKSDALE AFB.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: ROLLER CHATTER IS PRESENT ALONG THE INBOARD EDGE THROUGHOUT THE MISSION. FAINT MINUS DENSITY DOTS SPACED 1.7" APART, ARE LOCATED 1.6" AND 5.5" FROM THE INBOARD EDGE THROUGHOUT. A CRESCENT SHAPED CREASE EXTENDS ABOUT 7" ACROSS THE FORMAT OF FRAME 0402 FROM THE OUTBOARD EDGE OF THE FILM. THERE ARE PLUS AND MINUS DENSITY AREAS ADJACENT AND PARALLEL TO THE CREASE. AN EMULSION BLISTER IS PRESENT IN FRAME 0253. A MANUFACTURING SPLICE OCCURS IN FRAME 0435 WITH ASSOCIATED STATIC, AND PARALLEL MINUS DENSITY STREAKS OCCUR IN FRAME 0433. ANOTHER MANUFACTURING SPLICE EXISTS IN FRAME 0968 WITH ASSOCIATED EMULSION DIGS.

C. 9L SIDE: TWO HEAVY PLUS DENSITY STREAKS 2.5" LONG AND 0.3" APART RUNNING PARALLEL TO THE MINOR AXIS OF THE FORMAT APPEAR ABOUT 3" FROM THE SUPPLY END ON TITLED FRAME 0002. MINUS DENSITY DOTS APPEAR 3.9" FROM THE INBOARD EDGE AND ARE SPACED AT 1.7" INTERVALS. THESE DOTS ARE PRESENT THROUGHOUT THE MISSION. A MANUFACTURER'S SPLICE IS PRESENT ON TITLED FRAME 1043 WITH ITS ASSOCIATED DEGRADATIONS ON TITLED FRAMES 1041

2 SEP 1966

DISTRIBUTION

Cy No.	Office	Action
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	FD	
	FSD	
	FCD-DCB	
	TID	
	WAE	
	PAG	
	DIANX-4	
	SEAC	
	WSA-LO	
	DIA-AF	

advance copy
sanitized